

Sparepart documentation



Ventilation flap

Prod. No.: 389005

Product details:

* For device series BPT E 12/18/24/30 H, please check whether retaining tube 386580 and O-ring 365428 are also required.
* For device series BPT 820/1020/1220 EB, please check whether retaining tube 365259 and O-ring 365428 are also required.
* The retaining tube and ventilation flap must be glued together. We recommend using adhesive 150012. The installation instructions can be found in the webshop or by contacting our technical customer service.